

OPA-S

EXTERNAL DISPLAY FOR CDC AND CRC HUMIDITY SENSORS

Art.-No. 2517141



- To calibrate the humidity sensors (+/- 10%)
- Pre-wired with plug – Plug & Play
- Displays the current humidity value
- Indication and reset of minimum and maximum values

POWER SUPPLY

Operating voltage	5V DC, 5%
Power consumption	max. 1VA
Connection	cable and plug are inclusive

ENVIRONMENT

Humidity	< 95% rF
Temperature	0..50°C

STANDARDS

Protection to EN 60529 /	IP 30 / III
Safety class	
CE	EN 61 000-6-1 EN 61 000-6-3